



Bits mit 7/16" Sechskantantrieb DIN 3126 / ISO 1173 – E 11,2 *



Kreuzschlitz Phillips® – zähhart

Modell	Best.-Nr.	PH #	L mm	Ø mm	VE
PH2-E11-75	111310	2	75	6	10
PH3-E11-75	111311	3	75	8	10
PH4-E11-75	111312	4	75	10	10



Kreuzschlitz Pozidriv® – zähhart

Modell	Best.-Nr.	PZ #	L mm	Ø mm	VE
PZ2-E11-75	112310	2	75	6	10
PZ3-E11-75	112311	3	75	8	10
PZ4-E11-75	112312	4	75	10	10




Sechsrund Torx® – zähhart

Modell	Best.-Nr.	TX #	L mm	Ø mm	VE
T30-E11-60	113320	T30	60	–	10
T40-E11-60	113321	T40	60	–	10
T45-E11-60	113322	T45	60	–	10
T50-E11-60	113323	T50	60	–	10
T55-E11-60	113324	T55	60	–	10
T60-E11-60	113325	T60	60	–	10
T30-E11-75	113310	T30	75	6	10
T40-E11-75	113311	T40	75	–	10
T45-E11-75	113312	T45	75	8	10
T50-E11-75	113313	T50	75	10	10
T55-E11-75	113314	T55	75	12	10
T60-E11-75	113315	T60	75	14	10




Sechskant Inbus® – zähhart

Modell	Best.-Nr.	SW mm	L mm	Ø mm	VE
A4-E11-55	115310	4	55	5	10
A5-E11-55	115311	5	55	6	10
A6-E11-55	115312	6	55	7	10
A6-E11-55	115317	7	55	8	10
A8-E11-55	115313	8	55	10	10
A10-E11-55	115314	10	55	10	10
A12-E11-55	115315	12	55	14	10
A14-E11-55	115316	14	55	–	10
A6-E11-60	115320	6	60	–	10
A8-E11-60	115322	8	60	–	10
A10-E11-60	115324	10	60	–	10
A12-E11-60	115326	12	60	–	10
A14-E11-60	115328	14	60	–	10
A17-E11-60	115330	17	60	–	10
A5-E11-90	115321	5	90	6	10
A6-E11-90	115323	6	90	7	10
A7-E11-90	115325	7	90	8	10
A8-E11-90	115327	8	90	10	10
A10-E11-90	115329	10	90	12	10
A12-E11-90	115331	12	90	14	10



Vielzahn XZN – zähhart

Modell	Best.-Nr.	XZN #	L mm	Ø mm	VE
XZN10-E11-60	116303	10	60	–	10
XZN5-E11-75	116310	5	75	5	10
XZN6-E11-75	116311	6	75	6	10
XZN8-E11-75	116312	8	75	8	10
XZN10-E11-75	116313	10	75	10	10
XZN12-E11-75	116314	12	75	12	10
XZN14-E11-75	116315	14	75	14	10



Weitere Infos auf unserer Website.

24/7

* Für direkten Maschinenanschluss, vgl. Tabelle „Zuordnung von Werkzeugantrieb und Maschine“.

E-Mail: info@zemo-tools.de • Tel.: +49 (0)40 303 989 100 • Web: www.zemo-tools.de

ZEMO
www.zemo-tools.de